



<b>Suggested Hole Sizes for AB,B and BP Thread Forming and BF,BT Thread Cutting Tapping Screws</b>					
<b>Nominal Screw Size</b>	<b>Hole Diameter</b>			<b>Closest Drill Size to Mean Hole Diameter</b>	
	<b>Max</b>	<b>Mean</b>	<b>Min</b>	<b>Drill Size</b>	<b>Drill Diameter</b>
<b>0-48</b>	0.049	0.046	0.043	56	0.0465
<b>1-42</b>	0.063	0.059	0.055	53	0.0595
<b>2-32</b>	0.077	0.072	0.067	49	0.073
<b>3-28</b>	0.090	0.084	0.078	45	0.082
<b>4-24</b>	0.103	0.096	0.089	41	0.096
<b>5-20</b>	0.114	0.107	0.100	36	0.1065
<b>6-20</b>	0.124	0.116	0.108	32	0.116
<b>7-19</b>	0.138	0.129	0.120	30	0.1285
<b>8-18</b>	0.148	0.138	0.128	29	0.136
<b>10-16</b>	0.170	0.159	0.148	21	0.159
<b>12-14</b>	0.194	0.182	0.169	14	0.182
<b>1/4-14</b>	0.226	0.211	0.196	4	0.209
<b>5/16-12</b>	0.289	0.270	0.251	1	0.272
<b>3/8-12</b>	0.356	0.330	0.310	Q	0.332
<b>7/16-10</b>	0.413	0.386	0.359	W	0.386
<b>1/2-10</b>	0.480	0.449	0.418	29/64	0.4531